



DORIN

RICAMBI
Spare Parts


Y6



DORIN



M\Compressore M\Compressor Y6





MCompressore
MCompressor
Y6

DORIN

Rif.	QUANTITA'								Codice Code	Descrizione	Description
	Y3060CB	Y3560CC	Y3560CB	Y4060CC	Y4060CB	Y4560CC	Y4560CB	Y5060CC			
1	1	1	1	1	1	1	1	1	1CC5022	Kit sospensioni completa	机脚
2	1	1	1	1	1	1	1	1	1CCC085	Mozzo pompa	泵毂
3	1	1	1	1	1	1	1	1	1CCD003	Valvola ritegno olio	止回阀
4	1	1	1	1	1	1	1	1	1CCE011	Pres. man. TEE 1/4" Sae	三通接头
5	2	2	2	2	2	2	2	2	1CCL010	Pres. man. TEE 1/4" Sae	三通接头
6	1	1	1	1	1	1	1	1	1CCN036	Bronzina centrale	主轴承
7	1	1	1	1	1	1	1	1	1CCQ010	Spia olio completa	油视镜
8	3	-	3	-	3	-	3	-	1CCS065	Testa aria completa	缸头
8	-	3	-	3	-	3	-	3	1CCS066	Testa aria completa	缸头
9	1	1	1	1	1	1	1	1	1CDP411	Staffa lato motore	底板
10	1	1	1	1	1	1	1	1	1CGA035	Guarn.coperchio motore	垫片
11	1	1	1	1	1	1	1	1	1CGE071	Guarniz.mozzo pompa	垫片
12	1	1	1	1	1	1	1	1	1CGF121	Guarniz.fondo carter	底板垫片
13	1	1	1	1	1	1	1	1	1CKB055	Bronzina mozzo pompa	轮毂轴承
14	1	1	1	1	1	1	1	1	1CKF061	Filtro aspirazione	吸气滤网+垫片
15	1	1	1	1	1	-	1	-	1CKG060	Collettore scarico	排气歧管
15	-	-	-	-	-	1	-	1	1CKG061	Collettore scarico	排气歧管
16	1	1	1	1	1	1	1	1	1CKM060	Coperchio motore	Electrical motor cover
17	2	2	2	2	2	2	2	2	1CKP005	Tappo scarica/carica olio	Screws for discharge service
18	1	1	1	1	1	1	1	1	1LCU031	Filtro olio completo	油过滤器
19	1	1	1	1	1	1	1	1	1LGA021	Guarniz.pompa olio	垫片
20	1	1	1	1	1	1	1	1	1LKC010	Pompa olio completa	油泵
21	2	2	2	2	2	2	2	2	1LKV025	Valvola sicurezza compl.	安全阀
22	6	6	6	6	6	6	6	6	1MCB031	Biella completa	连杆
23	6	-	-	-	-	-	-	-	1MCD721	Kit biella-pistone compl.	连杆活塞组
23	-	6	-	-	-	-	-	-	1MCD724	Kit biella-pistone compl.	连杆活塞组
23	-	-	6	-	-	-	-	-	1MCD722	Kit biella-pistone compl.	连杆活塞组
23	-	-	-	6	-	-	-	-	1MCD725	Kit biella-pistone compl.	连杆活塞组
23	-	-	-	-	6	-	6	-	1MCD723	Kit biella-pistone compl.	连杆活塞组
23	-	-	-	-	-	6	-	6	1MCD726	Kit biella-pistone compl.	连杆活塞组
24	6	-	-	-	-	-	-	-	1MCE835	Pistone completo	活塞
24	-	6	-	-	-	-	-	-	1MCE836	Pistone completo	活塞
24	-	-	6	-	-	-	-	-	1MCE837	Pistone completo	活塞
24	-	-	-	6	-	-	-	-	1MCE838	Pistone completo	活塞
24	-	-	-	-	6	-	6	-	1MCE839	Pistone completo	活塞



M\Compressore
M\Compressor
Y6

DORIN

Note - Notes

n°ESP.COMM.Y6

Data di origine 23/02/2007

Data revisione

Rev. 00



M\Compressore
M\Compressor
Y6

DORIN

Note - Notes

n°ESP.COMM.Y6

Data di origine 23/02/2007

Data revisione

Rev. 00



OFFICINE MARIO DORIN S.p.a.

50161 COMPIOBBI - FIRENZE (ITALIA)

VIA ARETINA, 388

TELEFONO 055 623211

TELEFAX 055 62321380

TELEX 570164 DORIN FIRENZE

INTERNET= <http://www.dorin.com> E-mail: dorin@dorin.com